

ABC WELLS & CO.

NAME SAM JOB# DRI1252018120011 ENGINE HAMMER

START DATE: 2017-06-14 START TIME 11:59:48 END DATE 2018-01-03 END TIME 3:15:45

HOLE SIZE 115mm # HOLES 24 DRILL FT 69m INJURY OR DAMAGE N

A1	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

A2	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

A3	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

A4	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

A5	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

A6	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

A7	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

A8	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

B1	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

B2	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

B3	
0-69	BLOCKED HOLE

B4	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

B5	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

B6	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

B7	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

B8	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

C1	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

C2	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

C3	
0-17	CINDERS
17-34	DIRT
34-51	SOFT ROCK
51-69	HARD ROCK

C4	
0-10	DIRT
10-28	SOFT ROCK
28-69	

C5	
0-69	

C6	
0-69	

C7	
0-69	

C8	
0-69	